
烟道直径, m	等面积环数	测量直径数	测点数
<0.3			1
0.3~0.5	1~2	1~2	2~8
0.6~1.0	2~3	1~2	4~12
1.0~2.0	3~4	1~2	6~16
2.0~4.0	4~5	1~2	8~20
>4.0	5	1~2	10~20



f ‘#

